Official Transcript of Proceedings NUCLEAR REGULATORY COMMISSION

Title: Advisory Committee on Reactor Safeguards

590th Meeting

Docket Number: (n/a)

Location: Rockville, Maryland

Date: Friday, January 20, 2012

Work Order No.: NRC-1387 Pages 1-93

NEAL R. GROSS AND CO., INC. Court Reporters and Transcribers 1323 Rhode Island Avenue, N.W. Washington, D.C. 20005 (202) 234-4433

	
1	UNITED STATES OF AMERICA
2	NUCLEAR REGULATORY COMMISSION
3	+ + + +
4	590TH MEETING
5	ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
6	(ACRS)
7	+ + + +
8	FRIDAY
9	JANUARY 20, 2012
10	+ + + +
11	ROCKVILLE, MARYLAND
12	+ + + +
13	The Advisory Committee met at the Nuclear
14	Regulatory Commission, Two White Flint North, Room
15	T2B3, 11545 Rockville Pike, at 8:30 a.m., J. Sam
16	Armijo, Chairman, presiding.
17	COMMITTEE MEMBERS:
18	J. SAM ARMIJO, Chairman
19	JOHN W. STETKAR, Vice Chairman
20	HAROLD B. RAY, Member-at-Large
21	SANJOY BANERJEE, Member
22	DENNIS C. BLEY, Member
23	CHARLES H. BROWN, JR. Member
24	MICHAEL L. CORRADINI, Member
25	DANA A. POWERS, Member

1	COMMITTEE MEMBERS (CONT.)
2	JOY REMPE, Member
3	MICHAEL T. RYAN, Member
4	STEPHEN P. SCHULTZ, Member
5	WILLIAM J. SHACK, Member
6	JOHN D. SIEBER, Member
7	GORDON R. SKILLMAN, Member
8	
9	NRC STAFF PRESENT:
10	DEREK WIDMAYER, Designated Federal Official
11	ALLEN HOWE, NRR/DORL
12	MEENA KHANNA, NRR/DE/EMCB
13	KAMAL MANOLY, NRR/DE
14	GERALD McCOY, R-II/DRP/RPB5
15	JOHN TSAO, NRR/DE/EPNB
16	
17	ALSO PRESENT:
18	GENE GRECHECK, Dominion Energy
19	ERIC HENDRIXSON, Dominion Energy
20	DAVID SUMMERS, Dominion Energy
21	
22	
23	
24	
25	

		3
1	TABLE OF CONTENTS	
2	Opening Remarks by the ACRS Chairman	5
3	Augmented Inspection Team Report on North	
4	Anna	6
5	Adjourn	
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		

PROCEEDINGS

2 8:30 a.m.

CHAIR ARMIJO: Good morning. The meeting will now come to order. This is the second day of the 590th meeting of the Advisory Committee on Reactor Safeguards. During today's meeting, the Committee will consider the following: Augmented Inspection Team Report on North Anna and preparation of ACRS reports.

This meeting is being conducted in accordance with the provisions of the Federal Advisory Committee Act. Mr. Derek Widmayer is the Designated Federal Official for the initial portion of the meeting.

We have received no written comments or requests for time to make oral statements for members of the public regarding today's sessions. There will be a phone bridge line. To preclude interruption of the meeting, the phone will be placed on a listening mode during the presentations and Committee discussion.

A transcript of portions of the meeting is being kept and it is requested that the speakers use one of the microphones, identify themselves, and speak with sufficient clarity and volume so that they can be

readily heard.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

Now I'd like to turn the meeting over to staff and I believe that would -- Dana is going to leave us through that, sorry.

Dana?

MEMBER POWERS: You do it so well. Thank you. This is an information briefing. I was asked to prepare any documents based on this briefing. I suppose if we want to, we can.

Most of you are aware -- what was it, August 23rd -- that there was an earthquake. Those of us who have experienced in California think that a 5.8 earthquake is not something to get too excited about, that East Coast earthquakes are a little different. It occurred near Mineral, Virginia, close to the North Anna Nuclear Power Station. The earthquake caused Units 1 and 2 to automatically shut down. There was a loss of offsite power. No damage was reported to But it was the first instance of an the system. exceeding operating reactor its design basis earthquake.

Consequently, there has to be a fairly extensive inspection prior to restart and what we're going to hear about is both what the licensee and the staff have done in connection with that inspection and

restart process.

To begin our discussions, I guess Allen Howe is going to give us an opening statement and then we will move to the licensee.

MR. HOWE: Thank you, and good morning.

I'm Allen Howe, Deputy Director, Division of Operating
Reactor Licensing in the Office of Nuclear Reactor
Regulation. We appreciate the opportunity to brief
the ACRS on the actions that were taken following the
earthquake that occurred near North Anna last August.

As you said, the licensee will provide an overview of their activities and then that will be followed by a staff presentation of the inspection and technical review activities that were performed following the seismic event.

Just very quickly, following the earthquake, NRC staff did complete numerous activities including an augmented inspection which evaluated the licensee's performance during the event. And we also conducted restart readiness inspections. In addition, we completed a comprehensive technical evaluation of the actions taken by the licensee to demonstrate that it was acceptable the units to restart.

Our inspection and technical evaluations covered a wide spectrum of technical disciplines and

there was very close coordination among the organizations that were involved in the review.

this time, I'd like to introduce the staff leads for the inspection and the technical review activities. To my left is Gerry McCoy. He's a Branch Chief in the Division of Reactor Projects in Region II and responsible for the Dominion Gerry led the inspection efforts on behalf of Region II and he'll be speaking about the inspection activities, including the AIT, the restart readiness inspection and the start-up monitoring. Meena Khanna, to the left of Gerry is a Branch Chief in the Office of Nuclear Reactor Regulation. She led the effort on technical review in the Office of NRR. She will also be providing the presentation describing the technical review efforts that took place during the activities leading up to the restart decision. We also have staff here in the audience should questions come up that can provide answers to any of the technical issues that may come up.

At this point, I'd like to turn the presentation over to Mr. Gene Grecheck from Dominion.

MEMBER POWERS: Gene, welcome.

MR. GRECHECK: Thank you. Good morning.

As Allen said, I'm Gene Grecheck. I'm Vice President

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

of Nuclear Development for Dominion. And I've met some of you in what is normally my role. I'm normally in charge of our new reactor projects, North Anna III in specific, but very soon after the August 23rd earthquake I was asked to take leadership role in the recovery and the licensing efforts to -- first to determine what the extent of damage at North Anna was and then to work with the NRC staff to obtain the necessary restart.

With me, I have Eric Hendrixson. Eric is the Director of Engineering at North Anna. And as a matter of fact, at the time of the earthquake, he was the Director of Engineering for the corporate office and was in the process of transitioning out to the North Anna site. So he was in a unique position, both from a corporate engineering standpoint and the station engineering standpoint to guide the engineering efforts.

Also with me is David Summers over in the corner. David is head of our licensing organization and was our primary point of contact with the NRC staff during your review.

So a little bit of a summary -- between August 23rd and November 11th when we received permission to restart the units, we devoted more than

1	100,000 hours of effort, both in on-site inspections
2	and engineering analysis. As you can see, we spent
3	over \$21 million in this process, so this was an
4	extraordinarily comprehensive and complete review of
5	the North Anna Station and its seismic response.
6	We'll talk a little bit in a few minutes about NRC-
7	endorsed guidance, but we exceeded the requirements of
8	the Regulatory Guide that we published some
9	MEMBER POWERS: Why did you feel a need to
10	exceed?
11	MR. GRECHECK: I'll get to that in a
12	moment, Dana. I think you'll see it because there's
13	a flow chart and I'll show you how we did
14	CHAIR ARMIJO: Yes, I'd be interested to
15	see that. Does that \$21 million include the cost of
16	repair of the damage?
17	MR. GRECHECK: To the extent that there
18	was repair, yes.
19	CHAIR ARMIJO: Yes, I know it was minimal.
20	I just wanted to know
21	MR. GRECHECK: It does, but as we'll see,
22	there was very little to repair. This is mostly
23	inspection, walk downs, analysis.
24	CHAIR ARMIJO: So it wasn't any hardware
25	repair, replaced

1 MR. GRECHECK: No. 2 CHAIR ARMIJO: Thank you. 3 MR. GRECHECK: So the primary finding was 4 that there was no functional damage to any safety-5 related systems at the station. Part of what we're going to talk about and 6 7 of what was interesting and Ι think educational for all of us in this is that we are very 8 9 used to talking about the design basis and as was 10 pointed out North Anna was the first station in the United States to exceed its design basis earthquake 11 12 while in operation. What we found is that that terminology of 13 14 design basis earthquake is useful and it's useful in It is a necessary underpinning 15 the purpose of design. 16 of designing a plant to respond to a postulated event. 17 But it is not very useful in terms of determining damage station after 18 actual to а an event has 19 occurred. The key factors in what caused seismic 20 damage are the acceleration which is typically what we 21 consider about the ground motion response. It's also 22 important to know what frequency that vibration is 23

occurring at and it is also very important to note how

long that strong motion was in place.

24

1 Now frequency and acceleration are taken 2 into account on the typical graph and you'll see that 3 in a moment, but duration is not. So when you have an 4 actual event without knowing the duration and without 5 looking at that duration it's not possible to simply 6 say oh, I had such and such acceleration at such and 7 such a frequency and be able to directly say what 8 response I expected at the plant. 9 As I said, seismic acceleration response 10 spectra are used to conservatively design plants, but don't take duration into account. But there is a 11 factor which has been in the literature for some time 12 now called cumulative absolute velocity which attempts 13 14 to do both. It attempts to integrate essentially the 15 energy that is imparted by the vibration over the 16 period of time that that strong motion existed and 17 then with a great deal of empirical evidence, it has been correlated, the CAV values against what has been 18 19 observed over hundreds of earthquakes around the world in terms of what actually happens when you have this 20 particular event. And we'll talk about that. 21 MEMBER BLEY: Are you going to talk about 22 that in some detail? 23 24 MR. GRECHECK: Yes.

MEMBER BLEY:

25

Okay, I'll wait until you're

done then.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. GRECHECK: Well, some detail.

MEMBER BLEY: Let me pose my question ahead of time. Maybe you can address it as you go through it. For some seismic analyses associated with risk assessments I've seen a lot of work looking at complete time histories of the -- all these factors over time and multiple cases of those to examine the capability of the equipment. If you can explain how well this single parameter does -- play it against those kinds of detailed kind of history considerations, I'd really appreciate it.

MR. GRECHECK: I'll try to do that. So this graph here is -- first should be familiar.

We've seen this a lot, graphs similar to this and it is also what caused the initial concern right after the event after this data became available. There's a number of curves on this, so let's walk through them. The bottom two, there's a red line and a purple line. Both of them look like a little trapezoid, those are the operational basis earthquake and the design basis earthquake for North Anna as described in the North Anna FSAR.

The purple one is the design basis earthquake. You can see it starts -- the axes on this

thing is frequency. This is a logarithmic scale and frequency, runs from essentially zero to 100 hertz and then the acceleration is measured as a fraction of gravity on the vertical scale.

We also hear a lot about a number and everybody wants to know what was the design basis number a plant was designed to and by convention that is the number anchored at 100 hertz. So it's whatever the value happens to be at the far right-hand side of the scale. So that purple graph you can see goes up to a peak of perhaps .36 or so G and then comes down and ends at .12 and so if you look at the literature you'll see that North Anna 1 and 2 have a design basis of .12G. So that's the first thing that when you're trying to explain to the public what the design basis of a plant is, and they read that it's .12G and then they hear that well, at some frequency, for example, that the acceleration was .4, they say well, you were four times the design basis and that's not at all correct because as you can see it various frequency.

The OBE, the operational basis earthquake, is just arbitrarily set at 50 percent of the DBE, so that's that lower curve.

The green curve up at the top represents

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	the synthesized curve for the IPEEE effort that was
2	done some years ago when the NRC staff asked all
3	plants to look at what were the to the ability of
4	plants to survive in events significantly larger than
5	the design basis. For North Anna that green curve
6	represents what the IPEEE looked at the North Anna
7	plants for and you can see that that is quite a bit in
8	excess of both the design basis and the blue and
9	orange lines which represent the actual measured
10	accelerations from this earthquake.
11	MEMBER CORRADINI: Gene, can you just say
12	that again? The green is what now?
13	MR. GRECHECK: The green was the basis for
14	the IPEEE review of the North Anna plants back during
15	the 1990s.
16	MEMBER CORRADINI: So it was the source
17	input to see if you'd serve the pot?
18	MR. GRECHECK: Right.
19	MEMBER BANERJEE: What was the basis on
20	which that line was constructed?
21	MR. GRECHECK: Eric, do you remember?
22	MR. HENDRIXSON: It was guidance given by
23	the NRC a number of years ago and I can't recall the
24	Reg. Guides on what to apply to the power station.
25	MEMBER BANERJEE: So it looks like it's

1	about a factor of two almost.
2	MR. GRECHECK: A little over two.
3	MR. HENDRIXSON: Two and a half.
4	MEMBER BANERJEE: Well, whatever it is,
5	but how did they arrive at that factor?
6	MR. GRECHECK: I really don't recall.
7	MEMBER CORRADINI: Can we ask the staff?
8	MEMBER BANERJEE: Yes, can we get that
9	answer. How was that curve established, the green
10	one?
11	MEMBER CORRADINI: The green one, yes. If
12	not now, eventually.
13	MEMBER BANERJEE: If not now, later.
14	MEMBER SHACK: Well, there were lots of
15	discussions in the '90s of what the seismic margin
16	should be and I think EPRI proposed one and a half.
17	The staff proposed two, maybe two and a half. And the
18	Commission came down with 1.67 as so my guess is
19	it's one of those floating numbers at the time.
20	MEMBER RAY: It was looking for
21	vulnerabilities that could be addressed. That was the
22	whole point of the exercise.
23	MEMBER BANERJEE: But there must be some
24	basis.
25	MEMBER CORRADINI: It's essentially two
I	1

1	and a half. I was just curious if it was just an
2	engineering judgment or if there was some technical
3	basis.
4	MEMBER POWERS: I don't know that it's two
5	and a half, Mike.
6	MEMBER CORRADINI: Based on Gene's
7	description, the red is 50 percent lower than the
8	purple and the green is 2.5 times bigger than the
9	purple
10	MEMBER BANERJEE: On the extreme right.
11	MEMBER CORRADINI: At the extreme right.
12	MR. HENDRIXSON: And that particular
13	curve is a function of your particular strata and
14	seismic activity and analysis.
15	MEMBER CORRADINI: So the green dependent
16	on the region of the country and geology and all kinds
17	of stuff.
18	I guess what I'm asking is the purple was
19	the one that was developed on region. Everything else
20	is a scale up is the way I interpreted it.
21	CHAIR ARMIJO: We have a staff member.
22	MR. HOWE: Good morning, this is Allen
23	Howe again. And we understand the question is what
24	was the basis for the development of the curve for the
25	IPEEE. And we're looking for someone to respond to

now and try to get back to you before the end of the 2 3 meeting today. 4 MR. MANOLY: This is Kamal Manoly with the 5 Division of Engineering NRR. The RLE, the Review 6 Level Earthquake, that's based on seismic margin 7 assessment that was done as part of IPEEE. 8 simple explanation it really reflects the capacities 9 for the safe one shutdown path and that is based on 10 the HCLFPF 95.5 percent and basically it tells you that that's the kind of capacity you expect 11 components in the one safe shutdown path. 12 components did not meet that review of earthquake and 13 14 they were evaluated independently as part of the restart effort. 15 It was the form abilities 16 MEMBER RAY: 17 identification that was the point of the exercise. MEMBER POWERS: For our purposes, we can 18 19 let that one float. Gene, just go ahead. MEMBER BANERJEE: What were the other 20 curves? 21 22 MR. GRECHECK: So the blue and the orange, the ones that are more irregular, those were the 23 actual measured data from our seismic instrumentation 24 in the Unit 1 containment. 25

that question to you. So we'll take that one right

1	MEMBER BANERJEE: So what's the orange and
2	what's the blue?
3	MR. GRECHECK: Orange is the we
4	measured in three directions, so east-west, north-
5	south and vertical. So the orange is the east-west
6	direction and the blue is the north-south direction.
7	MEMBER CORRADINI: And where is the
8	vertical?
9	MR. GRECHECK: The vertical is not on this
10	graph. It's a different graph because actually the
11	design values are different, so I just chose to use
12	those.
13	MEMBER BANERJEE: So the purple and the
14	reds were for horizontal acceleration?
15	MR. GRECHECK: Correct. There's a similar
16	graph for vertical. I just didn't
17	MEMBER BANERJEE: Is it the same order of
18	magnitude?
19	MR. GRECHECK: Yes.
20	MEMBER BANERJEE: It's sort of more or
21	less isotropic at acceleration, that's the assumption?
22	MR. GRECHECK: Presumption.
23	MEMBER BANERJEE: Presumption.
24	MR. GRECHECK: So a couple of things jump
25	out at you here is that certainly at some frequencies
l	1

the actual measured acceleration exceeded what the design basis curve showed, but you can see that it was enveloped by the IPEEE curve so we had this data right at the beginning, so we said okay, it exceeded the design basis. It was less than IPEEE so we would have expected at a very, very first level that we should not expect to see significant damage to the plant, but this was very early.

A couple of other things to point out is that one of the lessons that is coming out of the work that has been done on East Coast earthquakes over the years that is part of the central and eastern United States' effort and part of the foundation for what may be Generic Letter 199 is that the frequency distribution of an earthquake on an East Coast earthquake at least is not at all what this curve predicts. You can see peaks at higher frequencies typically around 20 hertz. This is what the models are predicting.

So even with this event, we were able to see these peaks at higher frequencies that previously at least during the initial licensing of North Anna 1 and 2 were not part of the model.

Any other questions on this graph?

All right, so now let's talk a little bit

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

about the actual event. Here again, we're looking at accelerations in the three directions, east-west, vertical, and north-south. This is an actual time history of the event as measured. The shaded area represents the design basis acceleration. And so you can see that right at the beginning of the event, at about two seconds into the event, we had a peak acceleration, but that peak acceleration was very short. The numbers on the side, you can east-west, the 3.1 seconds, 1.5, and 1.0, that is the definition of strong motion which I think represents 70 percent of all the energy was released during that period. That's a standard definition of strong motion.

You can see that that strong motion essentially was something between one and three seconds. And the actual peaks, for example, in the north-south direction you can see some very, very sharp peaks that exceed the design basis level, but there's essentially one point there. So what you had was a single event where something had a single sharp acceleration, but then for the vast majority of this event was essentially background.

This surprises many people because, for example, my office is at our Innsbruck office about 40 miles from the plant and I felt this event and it was

1	a long time. I mean you stood there and you were very
2	much aware of the fact that something was happening.
3	But the thing that struck me after I saw this is that
4	by the time you were aware that something was
5	happening, the event was over, the event of
6	significance. So for 20 or 30 seconds or so you felt
7	vibration, but the strong motion was long gone by the
8	time that you were even aware that something had
9	really happened because it was a very, very short
10	event in terms of strong motion.
11	MEMBER CORRADINI: And that's a definition
12	that the staff uses as part of licensing or is that
13	something more scientifically
14	MR. GRECHECK: It's not part of the
15	license. The license is based on the design spectrum
16	which is what we were talking about before.
17	MEMBER CORRADINI: So this is just
18	analyzing
19	MR. GRECHECK: This is analyzing actual
20	measures
21	MEMBER CORRADINI: That's the definition.
22	If somebody said what is strong motion okay.
23	MEMBER POWERS: So one of the problems of
24	our design basis evaluation is just what Gene brought
25	up is we do frequency and acceleration. We don't do

1 duration. And that's something for us to think about. MR. GRECHECK: Now for the purpose of 2 design, a duration has to be assumed and depending, 3 4 for example, if you're going to do a shaker table 5 test, and you have to shake it for some period of time 6 and typically those times are in the 30-second range 7 So what you do is you shake your test object at the maximum design acceleration for that entire 8 9 So there is a duration that is part of time period. 10 the design effort, but that duration is a very long duration and so you can't say it has nothing to do 11 But the thing is is that in order to with duration. 12 be able to say how does what actually happen compare 13 14 to what I tested for, what I designed for, you need to look at duration and that is not -- that's not part of 15 16 the quoted design basis. POWERS: 17 MEMBER We have very long durations in Pacific Rim earthquakes. 18 19 MR. GRECHECK: Yes. MEMBER POWERS: Thirty seconds is not a 20 long time for the Pacific Rim. Again, it's a function 21 of where you are and what the geology -- do you know 22 what geological source the earthquake was from? 23 24 MR. GRECHECK: No, not specifically. There is no identified -- as I said, two is not 25

1 uncommon.

(Laughter.)

MR. GRECHECK: There's no identified seismic fault or anything that this was identified with. And again, I'm getting off into non-scientific things here, but in general, what I understand about East Coast events is that, of course, there are no tectonic, active tectonic plates on the East Coast, but there were a long time ago. And the seismic event, the action that created say the Appalachian Mountains way, way back left a lot of residual stress in the rock. And what we're seeing is just this relieving of residual stress somewhere in the rock that is there. But there's no identified feature that's associated with that.

MEMBER CORRADINI: But Dana said something I didn't hear. So Dana, your point was the 30 seconds is an assumed and that given historical things could be considered short or long.

MEMBER POWERS: Depends on where you are and what kind of earthquake you have.

MEMBER CORRADINI: But from a testing standpoint that's a pretty typical order of magnitude that people test at.

MEMBER POWERS: I'm not familiar enough

1	with shaker table to tell you a definitive answer.
2	MEMBER CORRADINI: I just didn't hear what
3	you said.
4	MEMBER BLEY: I think that's correct.
5	That's about right.
6	MEMBER RAY: They go as long as 45
7	seconds. I did a shaker table.
8	MR. GRECHECK: Certainly for our testing
9	that we were able to go back and look at, but that's
LO	the time frame.
L1	So to put this cumulative absolute
L2	velocity in some perspective, the blue bars on this
L3	graph represent the calculated CAVs for the three
L4	directions for the North Anna event. The cumulative
L5	absolute velocity, if you calculated one for the
L6	design basis, would be the yellow bars. And the green
L7	bars represent again a calculated CAV if you assumed
L8	the IPEEE event over the time period.
L9	So
20	MEMBER BANERJEE: And the yellow and the
21	green are integrated over 30 seconds?
22	MR. GRECHECK: Yes.
23	MEMBER BANERJEE: And the other one is
24	MR. GRECHECK: what we measured.
25	CHAIR ARMIJO: So it's the negative

1	acceleration and the positive acceleration are all
2	MR. GRECHECK: It's all integrated.
3	MEMBER CORRADINI: So it's the absolute
4	MEMBER RAY: Does the licensing basis give
5	you the duration that you use here for the DVE, the
6	yellow bar?
7	MR. GRECHECK: Yes, well, it does in the
8	embedded Reg. Guides that are subtiered to the higher
9	level.
10	MEMBER RAY: But I would suppose those
11	post-date North Anna's design, don't they?
12	MR. GRECHECK: Probably not. I think
13	probably some of this was already there.
14	MEMBER CORRADINI: I didn't understand
15	your question. Are you talking about the black line
16	or the yellow
17	MEMBER RAY: The yellow line. I just
18	wondered where they got the duration from because my
19	experience is those durations that they would have
20	used came after North Anna was licensed.
21	MR. GRECHECK: There had to be a basis for
22	the testing that was done for the North Anna equipment
23	which, like I said, was in that 30-second range. So
24	I'm assuming there was some regulatory basis.
25	MEMBER RAY: Yes. That's fine.

MR. GRECHECK: There's a line here called the regulatory limit and that number is extracted out of the Reg. Guide that was issued and we'll talk about that Reg. Guide in a few minutes. That Reg. Guide specified a level of .16 as a cumulative absolute velocity number. And that Reg. Guide is based on EPRI document. And the EPRI document says that if you show that it was .16, then you're using this empirical evidence that I was mentioning before where they looked at all of these earthquakes, hundreds of earthquakes around the world.

It was stated that no observed structural damage had ever been seen to an engineered structure at that level. So you have a very, very high confidence that you're not going to see damage certainly to a seismically-designed structure when what they call a commercially-designed structure had never seen any damage at that level.

Now there's a number of CAV limits out there that are talked about. The .16 value was specified by the staff when they endorsed the EPRI document. EPRI had originally proposed a value of .3,looking at a longer event. The staff had some questions about that so they limited the scope of the event and said well, with a shorter time period we're

1	going to use .16.
2	In our conversations with EPRI subsequent
3	to this event, they're saying that our time history
4	looks more like what they were thinking about in terms
5	when they specified this .3 number. And so from their
6	perspective, the more appropriate number
7	MEMBER SHACK: I thought the .16 was also
8	based on a filtering that you threw out accelerations
9	that were too low.
10	MR. GRECHECK: That's correct, yes. Too
11	low over a
12	MEMBER SHACK: Point three
13	MR. GRECHECK: Had all of that.
14	MEMBER SHACK: Had everything.
15	MR. GRECHECK: But if you looked at our
16	entire event and you looked at all of that low
17	MEMBER SHACK: I guess that was my
18	question, was yours computed with the filtering?
19	MR. GRECHECK: This was. What you see
20	here was calculated with the filtering and was
21	compared against the .16 value.
22	The reason I bring that up is because it
23	is
24	MEMBER BANERJEE: The filtering is a
25	threshold?

1	MR. GRECHECK: It's a threshold.
2	MR. HENDRIXSON: The way it works is you
3	calculate, integrate over all the time the absolute
4	value and you exclude the tail end if over a duration
5	of one second all the vibrations were less than
6	0.025Gs. So you have to go whole second with less
7	than 0.025Gs.
8	CHAIR ARMIJO: If you didn't have the
9	filtering, how much greater would the regulatory limit
10	be in your
11	MR. HENDRIXSON: About .23 for the worst
12	vibration which was the north-south which is the one
13	on the furthest
14	MEMBER CORRADINI: So the blue would have
15	gone from whatever it is to about .23?
16	MR. GRECHECK: It would have gone from .17
17	to about .23.
18	MEMBER CORRADINI: And when you do the
19	filtering, you do it with the yellow and the green.
20	You did it just with the actual data?
21	MR. HENDRIXSON: Correct.
22	MR. GRECHECK: But again, that .23 would
23	be compared against a .3. Why is that comparison
24	important? Because the Reg. Guide basically states
25	that if you are below that limit, then by definition

1	you have not exceeded the OBE. Not the BBE, the OBE.
2	By definition, you have not exceeded the OBE. So in
3	the case that we were having here, we barely exceed
4	the OBE value in one direction and that's what led to
5	this entire discussion.
6	MEMBER BANERJEE: Now when you talk about
7	this, maybe you perhaps clarify. You said that no
8	seismically-designed structure had failed below this?
9	MR. GRECHECK: No commercially
10	MEMBER BANERJEE: Or no commercially
11	MR. GRECHECK: No commercially-designed
12	structure had failed above below .16.
13	MEMBER BANERJEE: Below .16. So a
14	building which has been designed to normal building
15	codes would survive this?
16	MR. GRECHECK: Yes, without structural
17	damage. You would have cosmetic damage, but you would
18	not have structural damage. And it has never been
19	observed. So it's with all of this data. The attempt
20	was to be able to come up with an empirical,
21	predictive value to say I can measure this very
22	quickly. You can measure this within an hour or so
23	after the event. You know what the CAV number was,
24	and you can immediately predict what you expect to be
25	able to find.

1	MEMBER BLEY: Gene, you just said
2	something that I can't been aware of. I thought the
3	focus came from Figure 4 with the spectra showing the
4	frequencies at which you exceeded. And you just said
5	that it was the CAV point here where you exceeded it
6	that really set this off. So can you clarify a little
7	bit?
8	MR. GRECHECK: Okay, from a legal
9	standpoint
10	MEMBER BLEY: Yes.
11	MR. GRECHECK: The regulations state that
12	if you exceed the design basis, then you have to prove
13	and I think Part 100 has some words in it that you
14	have to prove that no functional damage occurred.
15	MEMBER BLEY: And those words are based on
16	the spectra?
17	MR. GRECHECK: They are.
18	MEMBER BLEY: Okay.
19	MR. GRECHECK: However, the words are in
20	the Reg. Guide that says that if you're below .16 then
21	you have not exceeded the OBE.
22	MEMBER BLEY: I didn't know that was there
23	or not.
24	MR. GRECHECK: It's not easy to reconcile.
25	MEMBER BLEY: Maybe we can ask the staff.
I	I

1	(Laughter.)
2	MR. GRECHECK: But I am pointing out that
3	that statement is there and I think that our it
4	would have been a different exercise perhaps if this
5	value had been 10 percent lower.
6	MEMBER BANERJEE: Is there a scientific
7	basis for this? Because essentially it's a velocity.
8	It's not an energy, right? So what is the scientific
9	basis of using that, rather than some form of an
10	energy spectra?
11	MEMBER CORRADINI: It's not a velocity.
12	It's an impulse.
13	MEMBER BANERJEE: It's a velocity.
14	MEMBER CORRADINI: If there's some fixed
15	mass that's being whipped around like this, it's an
16	impulse.
17	MEMBER BANERJEE: Well, under repeated
18	forcing. But eventually it's the velocity, that's
19	what it is.
20	MEMBER CORRADINI: Perhaps.
21	MEMBER SHACK: You have acceleration, you
22	get a velocity.
23	MR. GRECHECK: And I think that's why the
24	term is in there, but again, I don't it is a weird
25	criterion

1 MEMBER BANERJEE: I can't see any obvious 2 scientific basis for it. There must be some. 3 MR. GRECHECK: If you read the EPRI 4 document, they do say it's empirical. It is not some 5 sort of fundamental value. I mean, if it's an 6 MEMBER CORRADINI: 7 impulse, you can make it look like an energy if you 8 put your mind to it. 9 MEMBER BANERJEE: No, you can't. You have 10 to square the velocity. MR. HENDRIXSON: I believe the basis is 11 the amount of -- the time it takes and the amount of 12 energy it takes to start a structure into a harmonic 13 14 when you can start causing damage. So if it's a short 15 pulse, then your entire systems and structures won't 16 start moving in a harmonic and causing damage to those So time is of interest, as well as the 17 structures. magnitude of the acceleration. And if you integrate 18 19 that over time, that gives you a feel for how much energy the structures are beginning to display. 20 And the .16 or .3, depending upon how one 21 calculates CAV is based on going out and looking at 22 engineered, non-nuclear, non-safety related, 23 24 engineered structures and how they behaved for various

earthquakes. For the most part in the Pacific Basin

is where most of the data is from.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. GRECHECK: All right, I'm going to move ahead and there was significant design margin.

We knew a lot of margin existed in the plant before we started, but this is just some of the examples of that. So the plant told the story. So here's all the analytical things. The analytics told us we should be in good shape. We don't really expect to see very much, but let's go and look.

So here's the first example. This is from the turbine building. This is on the turbine deck. The turbine building is a non-seismic structure at This is on the top floor. As you know, North Anna. as you go up in elevation, the accelerations are magnified and you get higher effects. There are these demineralizer tanks to give you a sense of the scale. You can see a man standing next to one of them, so these are pretty tall tanks, high center of gravity, high center of mass. They are supported on some relatively spindly angle iron supports that you can see there.

And on the right-hand picture is a magnified view of the bottom of one of them. This represents the most serious structural damage that was seen at North Anna.

1	MEMBER POWERS: This was it?
2	MR. GRECHECK: This is it. I had a <u>New</u>
3	York Times reporter, Matt Wald, who came to the site
4	about a week after the event, and he had a photograph
5	with him. The photographer was looking forward to
6	being able to take Pulitzer Prize winning pictures of
7	the damage. And he was very disappointed when I
8	pointed to this and said that's it.
9	MEMBER BANERJEE: Was he able to spin this
10	into some horror story?
11	MR. GRECHECK: Actually, it was a very
12	positive story.
13	MEMBER SHACK: Is this 12 inches by 12
14	inches, this pedestal?
15	MR. HENDRIXSON: I believe it's a 6 by 6
16	pedestal, and 3 by 3 web steel above it.
17	MR. GRECHECK: And so clearly, there was
18	movement and there was some spalling of the corner of
19	the concrete here, but this is it.
20	The next represents what was reported in
21	Bloomburg this day as a crack in the North Anna
22	containment wall. This is an interior wall. And the
23	crack that you can see running horizontally across the
24	top of the picture is a crack in grout across two

pored concrete slabs. This was simply a grout that

1 was placed during construction, but you could paint The grout did crack along -- a pretty long 2 the wall. 3 distance, probably maybe 20 feet or so, a horizontal 4 distance. But this was not structural. It was not in 5 the concrete. It was in the grout. MEMBER BANERJEE: How did Bloomburg News 6 7 report this? 8 MR. GRECHECK: It was reported as a crack 9 discovered in North Anna containment wall. 10 Finally, we have dry-cask storage at North Anna and these are -- at least partially, are these 11 vertical casks that you can see in the upper picture. 12 A few days after the event, we did go out to the pad 13 14 to look and saw evidence that the casks had actually 15 You can see there's a ring there on the 16 That's where the cask had been originally. That's about four and a half inches or so of 17 horizontal displacement. These casks are about 100 18 19 tons, but they're not restrained in any way. just sitting on the pad. 20 Your first glance is oh, why did this 21 But again, you're talking about a smooth bottom 22 tank on a concrete -- relatively smooth concrete pad. 23 24 The pad itself is seismically designed.

25

didn't see any damage.

The casks are monitored for

1	leakage across their seal. There was nothing detected
2	there. But it did actually
3	MEMBER SKILLMAN: How many of the casks
4	moved?
5	MR. GRECHECK: Out of the 27 casks there,
6	I think 24.
7	MR. HENDRIXSON: All but two.
8	MR. GRECHECK: Two or three.
9	MR. HENDRIXSON: Four and a half inches
LO	was the maximum, somewhere
11	CHAIR ARMIJO: And they all moved semi-
L2	uniformly or did they vary?
L3	MR. GRECHECK: It was just the example
L4	that a lot of people have given us, some of us will
L5	remember the old football games where you had the
L6	vibrating table. That's exactly what happened.
L7	MEMBER SKILLMAN: I'd like to go back to
L8	your first slide, 9 here, please. Four years ago, NRC
L9	published Reg. Guides 148, 160, and 161. And that was
20	the industry's introduction to active seismic. And as
21	Harold said, you could shaker table at 45 seconds and
22	people made their way to Alabama to use the shaker
23	tables down there.
24	One of the tricks we all learned was we
25	had a component with a high natural frequency and

you'll find those tanks have a very high natural frequency. The way you protected them was by putting them on spindly legs. And if you could drop below three or above 30 hertz, you could actually make the large components become insulated from the ground motion and they wouldn't dance.

I would just offer what you see there on

that connection which is the angle iron to the floor is how the concrete reacted to the bending that came down from a large overburden from the high mass above But what we did for all the NSSSs is try to go to it. extremely strong structures extremely orfragile legs that would let the ground motion move under the components. And it appears as though a number of these images that you've shown identify components that have effectively been insulated from the ground motion because the legs are so spindly and those took the movement. But I believe that that's what we're seeing here.

MEMBER STETKAR: Gene, did you see any inplant electrical effects?

MR. GRECHECK: No.

MEMBER STETKAR: Does North Anna have still pretty much old style relays or have they been replaced with solid state --

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	MR. GRECHECK: It's been replaced. It has
2	the original Westinghouse solid state protection
3	system that was
4	MEMBER STETKAR: Okay, so your protection
5	system is solid state. What about switch gear and
6	stuff?
7	MR. HENDRIXSON: It's a combination of
8	both technologies. Relays and lots of solid state
9	devices.
10	MEMBER STETKAR: Are the relays that you
11	still have pretty small light-weight relays?
12	MR. HENDRIXSON: A combination of both
13	I call them the ice cube relays as well as the
14	Westinghouse.
15	MEMBER STETKAR: Your peaks are kind of 15
16	and 30 hertz or so. Thanks.
17	MR. GRECHECK: All right, regulatory
18	guidance. We talked about this a little bit, but
19	we'll talk now about the process that we went through
20	to determine what we needed to do at the plant post-
21	event.
22	Again, the EPRI during the 1980s developed
23	NP-6695 with guidelines for nuclear plant response to
24	an earthquake. It was an excellent document, about a
25	100-page manual essentially. You open it at the

beginning and you follow it. It was an excellent document for the case we had.

We have been working with EPRI now to provide them some OE on this and I think they're going to make some changes to it based on some of the experience because again, this was the first time we were able to place this document into actual use at an operating plant.

During the 1990s, the staff endorsed this document in two Reg. Guides, 1.166, Pre-Earthquake Planning and Immediate Actions Post-Earthquake; and then the 1.167 which was really the most useful one, Restart of the Plant Shutdown by a Seismic Event. And for the most part with some very, very minor exceptions endorse the use of the EPRI document.

All right, so if you go into the EPRI document, I'm going to show you two flow charts that basically take you through what EPRI says you should do post-event. So here's the immediate actions. We start up at the top. You feel the earthquake. Does the plant trip or not? Again, contrary to, for example, this is not -- these are not the Japanese units. There are no seismic trips in this plant.

There are no seismic sensors that can cause a reactor trip. So a reactor trip will be caused by some thing

1	that is a result of the vibratory motion.
2	In North Anna's case, the plant tripped on
3	a negative rate flux, nuclear instrumentation trip and
4	we could get into a lengthy discussion about that
5	MEMBER STETKAR: You dropped rods.
6	MR. GRECHECK: We did not drop rods.
7	MEMBER STETKAR: You didn't drop rods?
8	MR. GRECHECK: We did not drop rods, but
9	we had differences occurring because of the vibration
10	of both the core internals and the water inside the
11	core were causing differences between the NIs on the
12	four sides. And the NIs interpreted that as a
13	negative flux.
14	Interestingly enough, the two units
15	tripped simultaneously and they both tripped on the
16	same two NIs showing the same differential.
17	CHAIR ARMIJO: Very interesting.
18	MEMBER BLEY: You have no seismic trips?
19	MR. GRECHECK: We have no
20	MEMBER SKILLMAN: All of your NIs were
21	operating?
22	MR. GRECHECK: All of the NIs were
23	operating and both units saw the exact same
24	accelerations in the same direction and the same two
24 25	accelerations in the same direction and the same two NIs saw the same

1	MEMBER SKILLMAN: That's remarkable.
2	CHAIR ARMIJO: Is there anyone following
3	up on that to really nail it down on the cause and
4	explain it?
5	MR. HENDRIXSON: Yes, we actually went
6	through a detailed root cause evaluation which is
7	docketed. It goes through the various things that can
8	create that trip.
9	MEMBER STETKAR: That's the first
10	indication is you got from those two channels.
11	MR. GRECHECK: That's what tripped the
12	plant. Within a second or so of that
13	MEMBER RAY: Excuse me, before you go on,
14	have you yet had a chance to reconcile that with the
15	impression one would have had from the CAV numbers you
16	put up there? In other words, you'd think this had to
17	propagate all the way down into the core internals and
18	so on, would have perhaps required a longer duration
19	event.
20	MR. GRECHECK: No, because we actually,
21	we were fortunate that we have some very high
22	resolution records on these NIs. They had a very,
23	very short time slice. And you can see the seismic
24	wave propagating through
25	the core at the time where it came

1	through. It's a pretty interesting graph to look
2	MEMBER RAY: The thing that's interesting
3	at this point in my mind is just that there's a lot of
4	damping and so on that has to be overcome and I would
5	have thought it required more duration. But that's
6	fine.
7	MR. GRECHECK: It's a very short event.
8	It comes and goes. The oscillations stop very
9	quickly, but by that time you've already met the trip
10	and
11	MEMBER RAY: There's a huge amount of
12	damping involved. So as soon as the excitation is
13	removed, it will stop like that.
14	MEMBER SKILLMAN: What consideration did
15	you give to relative motion inside the reactor vessel
16	of the reactor internals against the reactor vessel
17	bumpers or core catcher?
18	MR. GRECHECK: It was looked at and it was
19	inspected.
20	MEMBER SKILLMAN: And evaluated?
21	MR. GRECHECK: And evaluated.
22	MEMBER SKILLMAN: Thank you.
23	MR. GRECHECK: Just to follow up on the
24	question about what the operators were aware of as
25	this occurred was not so much what they were aware is

1	that about a second later we lost offsite power
2	because our over-pressure protection relays in our
3	transformers picked up the vibration, saw that as a
4	sudden pressure in the transformer, and tripped the
5	transformers offline. So about a second after the
6	reactor trip, we lost offsite power.
7	MEMBER CORRADINI: So regardless of the
8	source of all this
9	MR. GRECHECK: We would have tripped
10	anyway.
11	MEMBER CORRADINI: I guess I wanted to ask
12	it differently. In terms of if the first event
13	didn't cause the trip, when you do some sort of
14	analysis, what do you think would cause the trip? The
15	offsite would have been the one you would have judged
16	would be the first thing that would have sensed it?
17	MR. GRECHECK: As a matter of fact, we
18	believe that was the initial response.
19	MEMBER CORRADINI: Initially, that's what
20	you thought was causing it until you investigated it
21	further.
22	MR. HENDRIXSON: The turbine trip was the
23	loss of offsite power. The reactor trip was the NIs.
24	The reactor trip signals didn't get to the turbine
25	trip before it tripped. The turbine trip signal

1	didn't get to the reactor protection before the NI.
2	MEMBER SKILLMAN: In this case, were the
3	sudden pressure switches your friend or your enemy?
4	MR. GRECHECK: Well, in this case, I think
5	they were our enemy, but you don't want to lose sudden
6	pressure protection either because they're there to
7	protect the transformer.
8	MEMBER SKILLMAN: Some units have gotten
9	rid of them.
LO	MEMBER STETKAR: Did you see any damage to
L1	insulators out in the switchyard, ceramic insulators?
L2	MR. GRECHECK: There was some.
L3	MR. HENDRIXSON: The real damage wasn't to
L4	the insulators themselves, the ceramic. They moved,
L5	they rocked and they I don't want to say broke the
L6	seal, but the rubber seal, a gap was made and oil came
L7	out.
L8	MEMBER STETKAR: On the transformers?
L9	MR. HENDRIXSON: On the transformers
20	themselves.
21	MEMBER STETKAR: Without break?
22	MR. HENDRIXSON: So they were still
23	intact, but we lost some oil as a result of that and
24	had to obviously reset the seals.
25	MR. GRECHECK: I think that's a very good

1	question in terms of the switchyard itself when they
2	did
3	MEMBER STETKAR: The switchyard itself
4	MR. HENDRIXSON: There was some damage.
5	There was some damage.
6	MEMBER SIEBER: What's the kV of the
7	switchyard?
8	MR. HENDRIXSON: It's 500, 345, and 230.
9	MEMBER SIEBER: So they're pretty big?
10	MR. HENDRIXSON: Yes.
11	MR. GRECHECK: All right, so following
12	this flow chart, you take the immediate operator
13	actions. You do operator walkdowns, and then the next
14	gate that you have to decide is did you exceed the OBE
15	or not? Obviously, we concluded that we did, so you
16	move to the next chart.
17	Here's where the differentiation occurred.
18	The blue on the left is where you start. And EPRI has
19	some definitions in their document about different
20	levels of intensity of damage. They go from zero to
21	three. Three is essentially catastrophic, you know,
22	massive structural damage. Zero has a number of
23	definitions, but basically says nothing significant
24	found.
25	You can do a walkdown of the plant and

1	make that determination very quickly. So very, very
2	quickly, we did walk down the plant. We said we're in
3	a zero case. And if you follow the chart for zero,
4	you can you go down in that area and say do you see
5	any damage to safety-related equipment? No. Do you
6	see any damage to earthquake damage indicators which
7	are the most susceptible equipment in the plant? No.
8	And you're done. You do your surveillance tests and
9	you start up the plant. That's pretty much the path.
10	MEMBER CORRADINI: The second diamond,
11	damaged earthquake damage indicators, does that mean
12	there's actually instrumentation on
13	MR. GRECHECK: You have equipment which
14	you have evaluated previously as being most
15	susceptible.
16	MEMBER CORRADINI: So some pre-analysis
17	says go look here, there, okay.
18	MR. GRECHECK: As a matter of fact, we
19	were talking about the IPEEE before. When you did the
20	IPEEE walkdowns, there were certain equipment that did
21	not you could not demonstrate 100 percent
22	confidence that they would survive that higher event.
23	So you know that these are the ones that are going to
24	be most susceptible.
25	MEMBER CORRADINI: And that's where you go

1 look.

MR. GRECHECK: That's where you go look.

MEMBER CORRADINI: Visual inspection,
okay.

MR. GRECHECK: So if you followed this flow chart for a damage intensity zero event, then this is essentially what you would do. This is a relatively short inspection. It doesn't take a great deal of effort. But this is what the EPRI document suggests is necessary for an intensity zero or damage intensity zero event.

However, if you evaluate it as being one, two, or three, then you go off on to the right-hand side. So what we did is we, just from the beginning, we just arbitrarily said let's assume we're in a Level

1. And that's what leads to this expanded inspection so everything else that you're going to hear about today, from us and from what the staff described is this expanded inspection effort where we just looked at everything we could think of and to verify that there was no damage.

MEMBER BLEY: Dana asked you in the beginning why you went beyond NRC requirement and you just again said you did. You haven't yet told us what led you to do that?

MR. GRECHECK: We did because we wanted -again, this is the first time this has ever happened
and we believed that for ourselves and anticipating
what the staff would need, we decided that we needed
more evidence than what this would suggest we would
have derived.

Remember, for us, again, we were in the same mindset as everyone else. We exceeded our design basis. We didn't see anything. But we had no prior experience with this and we're saying what do we need to do to prove to ourselves, even not considering what the staff's questions were going to be, that we don't have any damage. And so we decided to do a Level 1 inspection.

So again, we went beyond this classification. We started providing the staff, I think about -- the event occurred on August 23rd. On September 7th we met with the staff, provided the plan of what we were going to do to discuss this process. Of course we, at that time, said that we had several weeks of inspections ahead of us before we were going to be done, but we presented that all to the staff and said here's what we're intending to do.

Over the next couple of months we had a great deal of interaction with the staff. As you can

see, we got about 130 requests for additional information, in many cases asking us for inspections and analyses beyond even what we had originally proposed and in many cases we did those. The staff will talk to you about the inspection teams and we've already talked about the root cause evaluation. All of this was part of this overall effort to get ready to restart the plant.

I'll give you a few more pictures and then we'll be done. Part of the inspection was to go look again, as we just talked about, where -- if we were going to find damage, where would you expect to find it?

This is a picture of the Unit 2 circulating water tunnel. This is a picture that you're not going to often see because normally there's hundreds of millions of gallons a minute traveling through here. But this is basically a horizontal concrete box that is underground. Again, if there was going to be lateral motion you would see it here because you've got this rectangular box here that would be susceptible to damage. There was no damage found in this tunnel. But we did take the opportunity of the outage to be able to go in here and do a very extensive inspection of this tunnel.

1 MEMBER SKILLMAN: Did you have to clean 2 this before you could make these images? MR. GRECHECK: Actually, if you see the 3 4 white spaces there, that's the cleaning that we did 5 for detailed inspections. That's what it looks like without cleaning for the majority of the wall. 6 7 MEMBER SKILLMAN: So it was not filled with slime and mussels and mud? 8 9 MR. GRECHECK: No. 10 MEMBER SKILLMAN: Thank you. MR. GRECHECK: They had both units down. 11 Unit 2 was scheduled for refueling -- a refueling 12 outage about three weeks after the event, 13 14 entered into the refueling outage early, defueled the Unit 2 reactor, looked at all the fuel assemblies as 15 16 they came out. Looked at fuel assemblies in the spent 17 fuel pool. Looked at new fuel assemblies which had been delivered to the site in anticipation of the 18 19 refueling. Did not see any fuel damage. 20 Buried piping, there was а lot $\circ f$ speculation again about what could be in buried 21 The picture that you see on the left here is 22 piping. a transition. It is very close to the safeguards 23 24 building. It's a transition between several buildings

and again, if you were going to have buried piping

1	damage, you would expect it to be in these relatively
2	short transitions between buildings. If the buildings
3	were going to be moving, this is where you expect high
4	stress locations to be. This is maybe what, ten feet
5	down or so?
6	MR. HENDRIXSON: Yes, I'd say more like
7	six or eight feet.
8	MR. GRECHECK: But anyway, we excavated
9	all the way down there to look at these locations
10	where we would have expected to see damage. Again,
11	did not see any damage to any of this.
12	CHAIR ARMIJO: Is that buried piping
13	inspection called for if you're under the EPRI damage
14	1 category or is that
15	MR. GRECHECK: I don't believe so.
16	CHAIR ARMIJO: So you actually went beyond
17	the EPRI 1.
18	MEMBER SIEBER: Do you have a way to
19	measure differential movement between buildings?
20	MR. HENDRIXSON: Yes. There's a survey
21	that we do and there's survey markers and we do that
22	also.
23	MEMBER SIEBER: Did you do the surveys?
24	MR. HENDRIXSON: Oh, yes.
25	MEMBER SIEBER: You do that periodically?

1 MR. HENDRIXSON: Correct, six months or a I forget the frequency. 2 3 GRECHECK: And there's many other 4 inspections that we are not even describing here. 5 mean we put people up in man baskets and inspected the entire exterior of the containment ball, looking for 6 7 anything there. I mean we did a lot of visual 8 inspections throughout the plant looking for anything 9 that could be interpreted as damage. 10 MEMBER SIEBER: Did you test or inspect penetration? 11 12 MR. HENDRIXSON: Yes. MEMBER SIEBER: Pressure test them? 13 14 MR. HENDRIXSON: Yes, the Type C test. 15 Here's an example of one of MR. GRECHECK: 16 those earthquake indicators. This tank is one of the 17 susceptible tanks that came out of the list of the This has this high confidence, low probability 18 19 failure HCLFPF value of only .19. So this would be anticipated to be something that would be done of the 20 first things to show damage. And again, there was 21 22 nothing see here. This is another low HCLFPF component 23 24 This is an as-found picture. You can see that there is not even any disruption to the insulation. 25

1	MEMBER CORRADINI: Just so I understand.
2	So when you did the green curve and you did that
3	analysis, did you tend to find large mass components
4	that would be the things that worried you or were
5	there small mass components like electrical relays or
6	cabinets or things that aren't as heavy, but if they
7	got wiggled at a different frequency, would really
8	cause a problem. Do you know what I mean?
9	MR. GRECHECK: Yes. We did corrective
10	actions to some of them, like for example, one of the
11	anticipated issues was that the suspended ceiling in
12	the control room which has one of those egg crates
13	diffuser panels, those could fall. So we fastened all
14	those together such that they would be less
15	susceptible to fall during an event.
16	There were cabinets that by tying the
17	cabinets together you were able to change their
18	frequency. There was a series of things that were
19	done in the post-IPEEE environment to try to fix those
20	things that could be.
21	MEMBER REMPE: When you started the diesel
22	generator, it had a leak and what was the cause of the
23	leak?
24	MR. GRECHECK: It was improper
25	maintenance. The flange had been improperly

1	installed.
2	MEMBER REMPE: Okay.
3	MR. GRECHECK: And that leak occurred into
4	its run. It was not right at start up.
5	MEMBER BROWN: Right.
6	MR. GRECHECK: All right, so summary, we
7	looked at 134 systems. We looked at 141 structures.
8	Forty-six of these susceptible components were
9	specifically looked at. Surveillance testing. We did
10	a comprehensive set of surveillance testing that
11	include MOV stroking, motor runs, just about anything
12	again. And again, not just looking for go, no go, but
13	looking for trending because we could look at the data
14	from the previous pre-earthquake test and say did we
15	see any change in behavior from pre-earthquake and
16	post-earthquake.
17	CHAIR ARMIJO: If you would go to your
18	fuel examination, Slide 18, the picture there. Was it
19	all visual or was there any kind of measurements, gaps
20	between the fuel assemblies?
21	MR. HENDRIXSON: It was a visual and an
22	enhanced visual and then with the close-up camera you
23	get those dimensions.
24	MEMBER CORRADINI: And you were looking
25	for some sort of bowing or
ı	I and the second

1 MR. HENDRIXSON: Yes, or deformation of 2 the ridge and things of that nature. 3 MEMBER BANERJEE: Did you go in with 4 endoscopic examinations, anything like that? MR. HENDRIXSON: Most of it was face-on. 5 MEMBER BANERJEE: Face-on. 6 7 MR. GRECHECK: So a few short-term actions 8 that we completed before start up. One of the issues 9 we discovered is that our seismic instrumentation 10 dates essentially back to the early 1970s. designed for rapid analysis and it is not a free-field 11 12 instrument. It's based in buildings. The primary data that we've been presenting to you here is from a 13 14 sensor that is in the basement of the Unit 1 15 containment right on the base map. 16 So some people have asked some questions 17 about was that truly free field and can you really I think we were able to demonstrate that compare it? 18 19 it was close enough. But subsequent to the event, we have installed a temporary free-field monitor on site, 20 away from any buildings. One of the nice things about 21 this is that you can see it's relatively small. 22 digital. It provides you the capability of 23 24 calculating CAV, for example, very quickly after an

And so in the future we'll be able to do the

event.

1	preliminary analysis much faster. And we've revised
2	our procedures specifically to tell the operators and
3	engineers how to use this equipment.
4	MEMBER SCHULTZ: Where did you locate it?
5	MR. GRECHECK: It's close to our training
6	center, so it's on the site, but it's in an open area
7	away from any buildings that could alter its response.
8	MEMBER SCHULTZ: Where there any other
9	findings related to the operational response, the
10	response of the operators, the response of the site
11	crew?
12	MR. GRECHECK: Actually, the site crew
13	performed in exemplary fashion. It was very, very,
14	very good response.
15	I think the staff will describe to you
16	some of the actions we agreed to and so I won't go
17	through these in detail. There's a Confirmatory
18	Action Letter which was issued to discuss some of
19	these long term
20	MEMBER SIEBER: Before you jump to that,
21	part of the story of the event was that you started
22	four diesel, had to shut down one of them because of
23	a leak. What caused the leak?
24	MR. GRECHECK: Joy just asked that
25	question. The flange had been improperly installed.

1 There was a gasket and a flange and that -- clearly --MEMBER SIEBER: That event did not cause 2 3 the --4 MR. GRECHECK: It was a prior maintenance 5 action that had caused the --6 MEMBER SIEBER: You have an extra diesel, 7 right? 8 MR. GRECHECK: And we started that diesel and that diesel functioned. 9 10 MEMBER SKILLMAN: Let me go back to question The way your Operating and 11 Steve's Maintenance teams performed, was the trigger for their 12 actions you're having entered the unusual event and 13 14 then having followed your procedures from the ground 15 motion to giving instructions to your people? Was 16 that the flow or did the shift supervisor say oh, my 17 qoodness, I've got a problem. I need everybody in here right now with their flashlight. 18 19 MR. GRECHECK: Well, it occurred on day shift on a Tuesday. So the shift manager, of course, 20 everybody felt the earthquake so he -- and we had a 21 dual-unit trip, so enter E0 appropriately. 22 for seismic event and we actually went into an alert 23 24 so we -- the emergency response team then directed the

damage control team to actually recover a steam-driven

1	aux feed pump that was out of service in the middle of
2	a surveillance test. And then the shift manager, of
3	course, directed his crew to secure the diesel. It
4	was a coolant leak and load the SBODs all on to
5	that bus.
6	MEMBER SKILLMAN: I'm asking a larger
7	question. You were in a situation where you had a UE
8	and you were following your procedures for the UE and
9	it turned out what triggered the UE was an earthquake.
10	MR. HENDRIXSON: Actually, were in alert.
11	MEMBER SKILLMAN: Or an alert, I'm sorry.
12	MR. HENDRIXSON: And the alert was
13	actually called based on shift manager discretion
14	because he said I felt an earthquake. I've got do a
15	unit trip. Something serious is happening here and I
16	need to activate the emergency response organization.
17	MEMBER SKILLMAN: So you called your
18	people up.
19	MR. HENDRIXSON: Right. Thank you.
20	MEMBER SIEBER: I want to go back to the
21	diesel one more time. When you do maintenance on the
22	diesel when you're on the surveillance test crew, no
23	leak at that time, right? How long was that
24	surveillance test?
25	MR. HENDRIXSON: It was at least three

1	runs. Each is an hour long, plus
2	MEMBER SIEBER: It's a start, load, and
3	run for an hour.
4	MR. HENDRIXSON: Exactly.
5	MEMBER SIEBER: You did not do anything
6	beyond that when you did the maintenance, right?
7	MR. HENDRIXSON: Those were the basic
8	post-maintenance tests.
9	MEMBER SIEBER: Didn't leak then.
10	MR. HENDRIXSON: Correct.
11	MEMBER SIEBER: Only leaked when the
12	seismic event, you concluded the seismic event didn't
13	cause it?
14	MR. HENDRIXSON: It actually didn't leak
15	for about 45 minutes. And then after that period of
16	time it began to leak.
17	MEMBER SIEBER: I guess operation is a
18	sort of a seismic event in and of itself as far as
19	it's concerned.
20	(Laughter.)
21	MEMBER SHACK: Gene, on North Anna 3,
22	there's a picture safe shutdown earthquake based on
23	our best modern knowledge and all our methods. It's
24	been reported that you even exceeded the safe shutdown
25	spectrum there, too. Is that right?

1 MR. GRECHECK: At low frequencies, yes. 2 I pointed out before that the new models tended to 3 focus at higher frequency. The model that was in use 4 at the time of the early site permit which is not the 5 CEUS model that is now being released, but at the time the early site permit which is in the 2003 time frame, 6 7 that model was -- did correctly predict an envelope, the high-frequency vibrations, but it appears to have 8 9 under predicted the low frequency. So we are 10 examining that now and we are going to apply the CEUS model to North Anna 3. 11 MEMBER BLEY: When you say "low 12 frequencies" what --13 14 MR. GRECHECK: Two to three hertz. 15 MEMBER BANERJEE: The curve in the 16 spectrum that you've shown, you said I think that most 17 of the systems that you examined would not have been damaged even by that green curve. What -- were there 18 19 some systems that would have been and which ones would be? 20 MR. GRECHECK: So we get into this seismic 21 margin confidence type thing that HCLFPF value that I 22 was pointing out before. So analytically, we came up 23 24 with a list of about 50 items that you could not say you had 100 percent confidence that they would survive 25

1	that event.
2	MEMBER BANERJEE: Typically, what were
3	these things, important things?
4	MR. GRECHECK: Yes. Many of them are
5	tanks. You have again high center of mass tanks. You
6	look at the way they're anchored to the ground. And
7	you say well, some of these might fail under those
8	kinds of accelerations. So I think it was mostly
9	tanks and
10	MR. HENDRIXSON: Invertors were in there.
11	MEMBER STETKAR: Did you look at end beds
12	on your
13	MR. HENDRIXSON: Yes.
14	MEMBER STETKAR: Are your switch gear up
15	high in the building?
16	MR. HENDRIXSON: We basically hand-over-
17	handed the entire switchyard and actually in-depth
18	inspections of the switch gear. The energizer go in
19	and hand-over-hand
20	MEMBER STETKAR: I don't know how they're
21	anchored.
22	MEMBER BANERJEE: Were these particularly
23	vulnerable to what part of that spectrum? Because if
24	you looked at it, the high frequency end was quite a
25	bit higher than the lower frequency. So was this

vulnerability coming from the low frequency part, the 1 2 high frequency part? 3 MR. GRECHECK: I think it was equipment 4 dependent. You would compare each piece of equipment 5 against its vulnerability, whether it's high or low. MEMBER BANERJEE: 6 And you could identify 7 this based on the frequency? MR. GRECHECK: You can calculate what the 8 9 natural frequency of that particular item is, so 10 again, you would know where the harmonics would occur. So things that are very massive, may have a lower 11 harmonic frequency than some of these smaller items. 12 So to wrap up again, acceleration criteria 13 14 were very briefly exceeded in certain directions, but 15 this was a very short direction earthquake. We had, based on previous evaluations, we had established the 16 17 safe shutdown systems, could handle accelerations above the design basis and I think this confirmed it. 18 19 No safety-related systems or structures or components required any repair due to this event that we saw and 20 basically we did an extraordinarily comprehensive 21 review of the station and didn't find any damage. 22 And so on the basis of that and like I 23 24 said in a very extensive review by the staff and many,

we ended

up

questions answered,

many

25

receiving

1	permission to restart the units September 11th and in
2	the week or so subsequent to that, we restored both
3	units to 100 percent where they are today.
4	MEMBER SKILLMAN: I've got a question. I
5	see in your first slide was 21 million at inspection.
6	What was your lost generation for the time you were
7	MR. GRECHECK: Actually, that's a very
8	difficult question to answer because by pure
9	happenstance, this was a very mild period. Late
10	August, early September, well, most of September in
11	Virginia was much cooler than it normally is. The
12	loads were down, so therefore it's kind of difficult
13	to specify what the financial, what the replacement
14	power cost was for that time period. Obviously, it
15	was substantial, but it was not as bad as it could
16	have been.
17	July was very hot and had it happened in
18	the months before, it would have been a much more
19	serious economic impact.
20	MEMBER SKILLMAN: Thank you.
21	MR. GRECHECK: Thanks.
22	CHAIR ARMIJO: Any other questions for the
23	speaker? In that case, we'll turn to the staff.
24	(Pause.)
25	MR. McCOY: Good morning. My name is

Gerald McCoy and I am the Branch Chief for Region 2 for the Dominion plants. And I led the inspection response to the earthquake in Mineral, Virginia.

When the earthquake occurred, the Senior Resident Inspector, Greg Kolcum, was in the control room at the North Anna Power Station and he was observing the recently completed surveillance Mr. Grecheck was talking about on the turbine-driven auxiliary feedwater pump. We also had another NRC inspector on site. His specialization was emergency planning. He was on site during the earthquake and he assisted in the response there on the site.

These inspectors observed the plant's response during the event and immediately notified Region 2. At the same time North Anna was declaring an alert, 14 other nuclear licensees were declaring NUEs due to the same earthquake. In response to these notifications, the NRC activated its Operations Center and the Regional Instant Response Centers to monitor the affected plants.

North Anna was the only site to experience reactor trip following the earthquake. The NRC subsequently learned that the ground movement during the earthquake exceeded the levels to which the plant was originally designed at certain specific

frequencies.

Later, on August 23rd, Region 2 dispatched an additional inspector to the site to assist in the inspection effort. Also, a seismologist and a mechanical engineer from here at White Flint were also sent to the site within days of the event.

Because of the elevated risk from the loss of offsite power from the failed diesel generator, an evaluation was performed in accordance with Management Directive 8.3 which is entitled "NRC Incident Investigation Program." And it resulted in the formation and dispatch of an augmented inspection team to the site on August 29th. And their goal was to better understand the circumstances of the event and Dominion's response.

In addition to the augmented inspection, a restart readiness inspection, and a start-up monitoring inspection were also conducted to assess the licensee's inspection process and to determine the condition of the plant after the earthquake.

Mr. Mark Franke, DR's Branch Chief from Region 2 led a team of seven inspectors, including a seismologist, two structural engineers, two electrical engineers, and two resident inspectors. The inspection was conducted during the period of August

30th through October 3rd, 2011. The purpose of the inspection was to conduct an independent review, collect factual information and evidence of what occurred at the plant as a result of the earthquake, to assess the licensee's response and identify any generic issues.

The team's primary focus was on the plant's response to the event itself, rather than on the evaluation of the plant to support eventual restart. However, during the time period covered by this inspection, Dominion was conducting tests and inspections of plant structures and components. Members of the augmented inspection team observed some of these inspections and documented their observations as part of the restart assessment process.

The results of the augmented inspection team were provided at a public meeting held near the North Anna Power Station on October 3, 2011. The team's observations of the event included the observation of the ground motion from the earthquake exceeded the plant's license design basis at certain frequencies.

At this point, no damage had been noted to any safety-related systems of the plant. The safety system functions were maintained during the

earthquake. The operators responded to the event in accordance with their established procedures and North Anna responded to the event in a manner which protected public health and safety.

MEMBER STETKAR: Gerry, your third bullet there says some equipment issues. Is that limited to the diesel or were there other items that you identified?

MR. McCOY: There were other items. It's the diesel itself. There was issues with the seismic monitors. In particular, I'm thinking about there was an issue caused by the power to the seismic monitors and the alarms. That's why they had to declare the alert on a call from the shift manager's advice from the earthquake itself because they didn't get the annunciator they were supposed to get, so we looked at that, too.

There was one Juliet diesel was exhibiting frequency oscillation, so the team noted that and we looked into that further. The alph auxiliary feedwater pump terry turbine lube oil level switch had an issue that we wanted to look at and it turned out just to be an alarm issue with an alarm that wasn't expected, so we looked into it and it made sense in the end.

1 MEMBER STETKAR: There were other things, 2 but those are things that other than the power for the seismic monitor, those are other things that could 3 4 occur during any what's called a plain vanilla trip. 5 MR. McCOY: Correct. MEMBER STETKAR: Thanks. 6 7 MR. McCOY: The next inspection the NRC conducted was what we called the restart readiness 8 9 This inspection was of Dominion's inspection. readiness to restart the North Anna units and have 10 occurred from October 5th to November 7th, 2011. 11 objectives of this inspection was independent evaluate 12 Dominion's assessment that no functional damage had 13 14 occurred to safety systems which included evaluation of the licensee's walkdown, their corrective action 15 16 follow up and the review of their actions to support 17 start up. This team was led by Mr. Andy Sabisch. 18 19 Mr. Sabisch is the NRC Senior Resident Inspector at the Oconee Nuclear Power Station. He led a team of 20 eight inspectors including participation from other 21 NRC regional and headquarters offices with experience 22 in structures, piping, electrical components and plant 23 24 operations.

The inspection included an independent

assessment of Dominion's inspections and testing of systems and components. A risk-informed sample of the plant systems or walkdown by NRC inspectors and these observations were compared with those made Dominion. The team reviewed the evaluation so what was found during Dominion's walkdowns to determine if the issues were properly categorized. The team also reviewed the licensee's plan for starting up the The results of this inspection provided an input into the eventual NRC approval to restart the plants.

The conclusions reached by this inspection team was that the licensee's inspection process was adequate to identify any damage which had occurred to the safety significant systems in the plant. The team members performed a limited number of inspections of risk-significant systems in areas and no significant damage was identified. The team conducted spot checks to verify that the licensee properly evaluated any damage which was identified during the license's inspection. The team did not identify any damage to safety-related equipment from the seismic event. Minor issues identified by the restart readiness team such as the identification and non-earthquake related damage which had not been entered into the licensee's

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1 corrective action process and enhancements which could be made to the two hotel emergency diesel generator 2 3 root cause evaluation. 4 MEMBER SCHULTZ: Excuse me, what are the examples you might give for the items that were not in 5 the Corrective Action Program? 6 7 MR. McCOY: Not in the Corrective Action 8 Program. There were cases that the inspectors, I 9 mean, you send inspectors out in the plant and they're That's what we encourage them 10 going to find things. The things they found were like they found 11 corkboard in odd places. They found damage to 12 insulation. It wasn't related to the earthquake 13 14 itself. It wasn't the case where two pipes were 15 hitting, but it's just damaged stuff and they talk to 16 the guy who is beside him and said hey, is this in the 17 corrective action system? And they said no, and they said why not? Isn't that the process? 18 19 So it was just a case of me sending inspectors out and finding issues and making sure 20 licensees got it on their list of things to correct. 21 But it wasn't related to the earthquake, so we just 22 put it in their process and carried on with our 23 24 inspection.

MEMBER BROWN: Did you question why it

wasn't there? Did they answer that?

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

The licensee -- there was MR. McCOY: concern. There was a concern in the discussion between myself and the licensee and it was -- it's not something we usually see with Dominion, so I was kind of concerned that the fact that all of a sudden now you guys aren't putting things in your corrective action process, what's the problem? And they did stop and have a rebrief for their employees and say we are having issues. We are here specifically to look at the earthquake damage, but we still have to follow So I think -- I attributed it to regular processes. They were focusing the loss of focus on their part. on the earthquake. They didn't quite see the other things our inspectors coming in with new eyes were seeing about their plant.

Next is a start-up monitoring inspection.

NRC continued the inspection process while the licensee was in the process of restarting the plant.

The inspection was conducted during the start up of both Unit 1 and Unit 2 from November 11th through November 29th, 2011. The objective of this inspection was to independently evaluate Dominion's assessment that no functional damage had occurred to safety systems through the observation of control room

activities, surveillance tests, and inspections of important plant systems as conditions change during start up.

This inspection was led by Mr. Rodney Clagg. Mr. Clagg is the NRC's resident inspector at North Anna Power Station. He led a team of seven resident inspectors from other nuclear power plants. This team concluded that the licensee's process ensured that the structure systems and components of the North Anna Power Station could perform their safety functions following the earthquake and would support a return to the safe power operation without undue risk of health and safety to the public.

inspection team This completed verification through the observation of control room activities and direct inspection of activities including mode changes, heat up, reactor start up, power extension for cold shutdown to rated thermal power. It also included direct inspection of operability determinations, surveillance testing, maintenance risk assessments, emergent work control, modifications, post-maintenance testing, and a review Corrective Action Program documents, partial inspection walkdowns of selected systems, structures, and components including secondary systems and other

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

activities as applicable. No additional earthquake-1 related damage was identified to the plant systems 2 3 during the start-up process. 4 I now invite Ms. Meena Khanna, the Branch 5 Chief for the NRC's Office of Nuclear Reactor Regulation to discuss the Agency's technical review 6 7 efforts. 8 MS. KHANNA: Thank you, Gerry. Again, my 9 name is Meena Khanna and I did lead the technical review efforts out of NRR. 10 There was a question earlier that I just 11 wanted to touch base on. There was a question about 12 And we found the quidance document. 13 the IPEEE curve. 14 It's NUREG-1407. So I just wanted to mention that to 15 So hopefully that will address it. And if you 16 need any additional information, we can ask our 17 seismic expert, Dr. Nilesh Chokshi, to help us out with that as well. Okay? 18 19 The restart requirements. The regulatory requirements governing this event are delineated in 10 20 CFR Part 100 Appendix A. Basically this states that 21 if the vibratory ground motion exceeds that of the 22 operating basis earthquake, then the shutdown of the 23 24 nuclear power plant will be required.

In addition to that prior to resuming

operations, the licensee will need to demonstrate to the Commission that no functional damage has occurred to those features necessary for the continued operation without the undue risk to the health and safety of the public.

I'd like to take a second here to also indicate that I will be interchangeably using the terminology of safe shutdown earthquake and design basis earthquake. They mean the same for North Anna. So if you near me say SSE, safe shutdown earthquake. That is the same as design basis earthquake.

As far as the technical review, the regulatory review guidance that the NRC followed was established in the mid-1990s. As you heard Mr. Grecheck address the Reg. Guide 1167 which is entitled "Restart of a Nuclear Power Plant Shut Down by a Seismic Event" which is endorsed by the EPRI NP6695 -- I'm sorry, which endorses the EPRI NP6695 guideline was also used. And that's entitled "Guidelines for Nuclear Plant Response to an Earthquake."

I'd also like to note that the EPRI guidelines does talk about guidance on what to do if the plant exceeds the OBE as well as design basis earthquake. Both short-term and long-term actions are addressed in the EPRI guidelines. In addition to the

EPRI guidelines and the Reg. Guide, we also took it one step further and used the IAEA Safety Report No. 66 which also addresses lessons learned from the International Plant which was the Kashiwazaki plant in Japan and this plant had also exceeded its design basis earthquake. So this provided valuable information to us in conducting our reviews, especially with respect to hidden defects.

MEMBER CORRADINI: So if I might just ask, so in the conversation with Gene, there was -- I don't want to call it an inconsistency, a difference between 10 CFR 100 and the Reg. Guide which points to the EPRI document in terms of -- maybe I'm misinterpreting, so I'm not sure if it's inconsistent or it's just a different term. Are you going to address that here?

MS. KHANNA: Yes, just the 10 CFR Part 100 basically just indicates that if you do exceed the OBE, then the plant will be required to be shut down and NRC approval needs to be addressed, needs to be sought from the licensee. However, the EPRI guidelines goes into what the plant needs to do to address what actions need to be taken once it's exceeded the OBE in licensing. Is that what you were getting at?

MEMBER CORRADINI: I'm probably going to

1 do this wrong, so let me try again. So the way you just explained it is we looked at this multi-colored 2 3 set of curves and then given the fact that they exceeded what they were designed for, that puts them 4 5 in a situation they have to look at things. But then they look at the Reg. Guide to decide what they have 6 7 to do in terms of -- Gene had a decision matrix. 8 MS. KHANNA: That's right and that comes 9 out of the EPRI guideline so the Reg. Guide endorsed 10 the EPRI guidelines. MEMBER CORRADINI: Let me posit one thing. 11 in the north-south -- I don't remember what 12 direction it was, the blue bar was slightly above the 13 That black line comes out of the Reg. 14 black line. 15 Am I correct in understanding that? And that Guide. 16 points to the EPRI document. So you -- based on some 17 natural event, you exceed what is their design base, but then once you go in terms of this only if that 18 19 blue bar gets above the black line do -- any more than a zero corridor inspection. 20 Am I interpreting that correctly? I want 21 to make sure I get this right. 22 KHANNA: I think you've got it 23 MS. 24 The EPRI quidelines will indicate to you

that the level, based on the amount of damage the

plant sees at the site, that basically tells them what level they need to go and when we're talking about the various levels that going to be in the EPRI guidelines. Does that help? Okay.

Okay, so in addition to the IAEA safety report, obviously we have great technical expertise here, so we also utilized the technical expertise that we had and that was really helpful with the area of fuels and on the evaluation as well, which I'll get into a little bit more detail later.

Eike I indicated, significant level of NRC effort was placed to independently evaluate the impact of the seismic event including structural and seismic experts throughout the Agency. We also dedicated a special restart team. We had several senior level advisors as part of this team dedicated project managers, so we took this very seriously and had a separate team that was working basically on this 24 -- I'm not going to say 24/7, but around the clock and doing what we needed to do.

The overall review and evaluation assessed the scope and the adequacy of the licensee's inspections, as Gerry had indicated, as well as the testing and the evaluations and the technical reviews were also informed by the inspections that Gerry had

mentioned earlier. And again, the staff did not identify any significant safety issues stemming from the seismic event.

As Allen had indicated earlier, the NRC's inspection assessment activities did involve a wide spectrum of technical disciplines and there was definitely coordination among the reviews and the inspection activities across the offices with the Agency.

Also, as part of this, I'd like to mention that we did come up with an action plan. We developed an action plan. There were so many activities going As you heard, the inspection activities -- there were audits done on the fuels that I'll talk about We have 2.206 petitions. As you can imagine there were quite a few public meetings, Commission briefings. And also what we wanted to do was make sure that we captured the short-term actions as well as the long-term actions and Gerry had mentioned that there were -- I don't know if he had mentioned it, but there were two generic issues that were identified out of the AIT inspection report and those were both with respect to the seismic monitoring instrumentation. what we've got in place right now is we're putting together an information notice to address those two

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

generic issues. So again, all these items are being tracked within our action plan. We also developed a com. plan because we believe that was important.

The NRC performed comprehensive independent technical review to ascertain whether it was acceptable for the North Anna plant to restart. This slide lists many of the technical areas that were reviewed which includes reactor vessel internals as well mechanical engineering structural electrical engineering. I won't go through all of this, but based on this list, you can see that almost every single technical branch in NRR was impacted and was involved in this review.

I'd like to highlight a few examples to demonstrate the independent nature of our review. address the integrity of the fuels, we did conduct audits of the fuel and I believe Tony Mendiola, his site and reviewed actually went the to Dominion's efforts for confirming the integrity of the In response to our review of Dominion's efforts, Dominion performed additional also calculations to demonstrate the integrity of the fuel assembly components to ensure that they were not compromised as a result of the earthquake.

With respect of our review of the piping

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

systems, Dominion performed additional analyses as well as to provide the NRC staff confidence that the earthquake did not adversely impact the piping and to ensure that the previous analyses were not invalidated as a result of the earthquake. For example, a leak before a break, and just ensuring that any prior existing flaws were not impacted by the earthquake as well.

Also, I'd like to mention that with respect to inspections of snubbers, Dominion had committed to doing functional testing of the snubbers with respect to Unit 2 and as a result of our questioning attitude, they also completed functional testing of the snubbers for Unit 1 as well.

And then later on in the presentation I'll talk about the long-term activities, long-term items that were addressed in the CAL and that was also due to the questioning attitude of the staff license renewal, was heavily involved in that because as you know, there was a license renewal issue for this plant. So there were several activities that came out of that that will be addressed in that Confirmatory Action Letter.

NRC staff conducted a safety review in accordance with the established acceptance criteria.

This was a first of a kind review. The staff -- this was very basically new to the staff. It was a complex review, so we wanted to ensure that we had consistent technical reviews across the office. So before we started review, we came and developed acceptance criteria and really what helped Inspection Manual Chapter 9900. That gave us good quidance and that's basically the operability and functionality assessments determinations resolution of degraded or nonconforming conditions. So that was the basis of our acceptance review And that really helped out. criteria. We made sure that we had Office of General Counsel involved and made sure that in every step that we were doing that they were watching what we were doing and making sure that we weren't doing anything illegal.

The NRC ensured that Dominion demonstrated that the plant is safe to operate prior to approving restart. And as we indicated earlier, the staff did not identify anything from our inspections or the technical review to preclude plant operations as a result of the seismic event. The results that were reviewed determined that the plants may be restarted safely and the bottom line was that the NRC was not going to allow plant restart until we were confident

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

that it would be operated safely.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

And as Mr. Grecheck indicated, on November the down 11, 2011, after plant was shut approximately 80 days, the Office Director of the Office of Nuclear Reactor Regulation issued restart approval decision for both North Anna Units 1 and 2. The decision was based on the staff's independent assessment which concluded that Dominion had acceptably demonstrated that no functional damage occurred to those features necessary for continued operation as a result of the August 23rd earthquake, thereby ensuring that there was no undue risk to the health and safety of the public.

I'm sure you've read our safety assessment. You can find that it's extremely comprehensive. We tried to make sure that we captured everything. Again, this was a one time -- this was a first of a kind event and we wanted to make sure we captured our technical review in case we needed it for knowledge transfer later on in the future. Also, we issued a confirmatory action letter to address the licensee's commitments for long-term actions.

The next few slides, I'm not going to go through each of the ten long-term actions that were identified in the CAL. However, I do want to

highlight a few items here. Dominion did commit to perform the long-term evaluations in accordance with the NRC endorsed guidance, so the EPRI guidelines do talk about long-term actions and that's what Dominion committed to. We completed our reviews regarding these evaluations and the long-term commitments are addressed in the NRC CAL which is also dated November 11, 2011.

As indicated earlier, as a result of the earthquake, the plant exceeded its design basis earthquake ground motion. To address this issue,

Dominion committed to update their final safety analysis report to include this new seismic ground motion as reflected in the August 23rd earthquake which is also addressed in Item 3 of the Confirmatory Action Letter and that's identified as multiple due dates.

With regards to Item 10 --

MEMBER RAY: Could you back up? Item 2 up there isn't very far off, March 31, 2012. And is there any insight at all on the source characterization? Does the NRC have any work in progress to look at that or are you waiting for a submittal?

MS. KHANNA: Kamal?

1	MR. MANOLY: This is Kamal Manoly with
2	NRC. That started to be addressed as part of the
3	50.54f letter that will be issued some time which
4	essentially is an extension of GI-199.
5	MEMBER RAY: Okay, so basically, it's not
6	going to be something special for this event.
7	MR. MANOLY: That's correct.
8	MEMBER RAY: Given all else that's going
9	on in that area.
LO	MR. MANOLY: Dominion committed that they
11	would follow whatever action comes out of the GI-199
12	effort.
L3	MEMBER RAY: Okay, it's just an
L4	interesting action item to have in a Confirmatory
L5	Action Letter.
L6	MS. KHANNA: You bring up a good point as
L7	well. There was close coordination with the Near-Term
L8	Task Force on the Fukushima and actually the seismic
L9	monitoring instrumentation, that was one issue that
20	they were going to be addressing as part of the
21	lessons learned, but they thought it would be more
22	appropriate for us to address it, so that's why we're
23	pursuing the information notice.
24	As Kamal indicated the GI-199 efforts, all
25	of that we're making sure that everything is tied

MEMBER RAY: It's just the date seems awfully close. That's why I asked.

I just wanted to highlight, MS. KHANNA: so item ten, the long-term commitment entails that Dominion will use the recent ground motion spectrum from the August 23rd earthquake in conjunction with basis the original design earthquake seismic qualification of new and replacement equipment. this was one item that we -- the staff was requesting of the licensee and wanted to make sure that for new and replacement equipment that they were considering the response spectra from the existing design basis earthquake as well as from the as-felt earthquake that was seen from the August 23rd earthquake.

the long-term commitments Aqain, identified consistent with those in the EPRT quidelines. However, you'll note that in the list there are a few that stem from the license renewal folks because there is a license renewal application So there are a few license renewal that was approved. commitments included. For example, MRP-227. again, as I mentioned the staff did issue an action plan and that's where we're going to be tracking the closure of all these CAL action items.

That concludes our presentation. I'll now

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

open it up for questions.

CHAIR ARMIJO: Item 7, you want them to do comparative calculated loads from the earthquake and the existing leak before break analysis. What drove that request in view of the condition of the plant?

MS. KHANNA: I'll give a high level -- I don't know if we have the appropriate person, but I believe what they want to do is any analyses that had been done for license renewal, they wanted to make sure that they were still valid. So I think they wanted to make sure that if there were any different stresses, but -- do you guys want to help me out, please?

CHAIR ARMIJO: Is anybody else -- well, I'm just wondering.

MR. TSAO: This is John Tsao from Division of Engineering. The reason we ask licensee to do recalculation of leak before break analysis is that leak before break is to satisfy GDC-4 and GDC-4 requires a Commission-approved leak before break analysis. Because of the seismic event we think that the loads, the seismic loads may increase and we are wondering whether the current leak before break analysis approved for North Anna still satisfies the

1	staff's recommended safety margin in the Standard
2	Review Plan 363. So this is a confirmatory analysis
3	to make sure that leak before break application is
4	still valid for North Anna.
5	CHAIR ARMIJO: Okay. It just seems like
6	the condition of the plant and leak before break
7	MEMBER SHACK: Remember, with leak before
8	break you have to postulate a big flaw that doesn't
9	really exist, so they're looking for that margin. So
LO	with the higher loads and the postulated big flaws, it
L1	has to demonstrate a margin. Even though it looks
L2	fine, you still need the analysis.
L3	MEMBER RAY: Higher loads resulting from
L4	this event or
L5	MEMBER SHACK: Just the seismic loading
L6	now seems to be somewhat higher than originally the
L7	spectrum has been exceeded.
L8	MEMBER RAY: By this event.
L9	MEMBER SHACK: By this event.
20	MEMBER RAY: You're talking about this
21	event though.
22	MEMBER SHACK: Right.
23	MEMBER RAY: Not some other change in the
24	design basis.
25	MS. KHANNA: This is specific to this
J	

1	event, right.
2	CHAIR ARMIJO: Okay, thank you.
3	MEMBER SHACK: That they advise, too,
4	Harold.
5	MEMBER RAY: I understand. But I'm trying
6	to keep them separate in my mind anyway.
7	MEMBER STETKAR: Meena, as part of the
8	lessons learned from this, do you anticipate any
9	revisions to Reg. Guide 166 and 167?
10	MS. KHANNA: That's a good question. Yes.
11	Research, right now is going through a revision of
12	Reg. Guide 1.667 and we're actually providing a lot of
13	feedback to that. The Reg. Guide does need to be
14	updated. It's been a while since it's been updated,
15	so there are a lot of lessons learned that we gain
16	from this review. Probably more robust than the Reg.
17	Guide. I think you'll see a lot of the RAIs that we
18	asked the staff is doing a great job.
19	MEMBER STETKAR: Anything on 1.166 as far
20	as planning and operations?
21	MS. KHANNA: To be honest with you, I'm
22	not aware of any. We haven't seen an update.
23	MEMBER STETKAR: Thank you.
24	MR. WIDMAYER: Meena, the Reg. Guides are
25	the Reg. Guides promote the EPRI document. Is

1 there's something going on where they're being reevaluated and updated? 2 3 MS. KHANNA: I'm not sure about that, but 4 what we will do is when we put the Reg. Guide out, if 5 we do any updates, obviously that would precede what's in the EPRI guidelines. So I haven't heard of any 6 7 updates of the EPRI quidelines, but I would think that 8 once we -- I don't know, David, if you would know, but 9 10 MR. MANOLY: In the Reg. Guides that endorses the EPRI 6.695, it endorses conditions and my 11 expectation is if EPRI does not revise the document, 12 we will add more conditions in the Req. Guide. 13 14 MEMBER BLEY: There was a discussion earlier 15 when the licensee here about was the 16 regulation requiring that you meet the design spectra 17 or that the spectra is met and the Req. Guide making a definition based on CAV that if you're within that 18 19 value of CAV you don't exceed the OBE. Is that an actual conflict? How is that 20 to be resolved and is this leading to any thoughts 21 about how the design basis will be formulated or 22 defined in the future for new reactors? 23 24 MR. MANOLY: This is Manoly again. you talk about design spectra, that is what's used for 25

1	the design of the structures and components and the
2	Reg. Guide talks about exceedance when you have an
3	earthquake that's felt. So what is the design tool?
4	I think we tried to articulate that point. The CAV is
5	a measure to determine the threshold beyond which you
6	should consider that you exceed the OBE.
7	MEMBER BLEY: So that is the basis for
8	staff looking at an actual earthquake and deciding if
9	you exceed the OBE.
10	MR. MANOLY: Yes, that's the Reg. Guide.
11	That's in the record. But the design for the plant is
12	the design spectra, the ASME, that's for the actual
13	design structure and components with the margins that
14	exist in the design process.
15	MEMBER BLEY: How is the requirement for
16	how long if the component is tested on a shake
17	table for the duration of the shaking arrived at and
18	is that something that NRC approves or is that
19	something that the licensee decides?
20	MR. MANOLY: Typically, the equipment are
21	tested by qualified by testing, some are qualified
22	by analysis. When you qualify equipment by testing,
23	you do it to one SSC and five OBEs.
24	MEMBER BLEY: And for what duration.
25	MR. MANOLY: The duration is usually

1	around 30 seconds typically.
2	MEMBER BLEY: It's not a requirement?
3	MR. MANOLY: I believe it's in the IEEE
4	44, but I believe the duration is around 30 seconds.
5	MEMBER BLEY: It's not something you
6	regulate other than may be referring to the IEEE?
7	MR. MANOLY: In Reg. Guide 100 Rev. 3, it
8	endorses the EPRI 344 for electrical equipment and now
9	it endorses the ASME fuel made for qualification of
10	the technical equipment.
11	MEMBER BLEY: It's a little more complex
12	than I can completely understand here on the fly.
13	MEMBER CORRADINI: But just to follow up
14	Dennis' question, given the fact you're going to have
15	lessons learned from his from how you connect the Reg.
16	Guides to the requirements, I think at least some of
17	us like to understand how all this is going to
18	MEMBER BLEY: That's kind of where I was
19	coming from.
20	MEMBER CORRADINI: Is that a fair way to
21	putting it?
22	MS. KHANNA: Yes.
23	MEMBER POWERS: Are there any other
24	questions?
25	MEMBER BLEY: Just a quick comment. Since

you pointed us to a NUREG for understanding the IPEEE spectrum, actually that Reg. Guide tells how the IPEEEs were done and says you can either do a seismic PRA which would develop a site specific hazard curve, or you can do an EPRI margin study or an NRC margin study. The NRC margin study refers you to another NUREG CR that develops kind of a generic spectrum for mild or moderate rock or soil site. I suspect it's over there, but that's not on the website.

MEMBER SKILLMAN: Mr. Chairman, I would like to make a comment. I'd like to compliment the staff and the Dominion team for really taking to heart an abundance of caution when it might have been another utility that would have arm wrestled, would have said we're so close to the CAV we really don't have to do anything. Independent of how much money was spent, this exercise has shown in this particular case how robust this machine is. But it has also demonstrated a nuclear safety attitude that at least I for one am very pleased to be around. So I want to say thank you.

MEMBER SIEBER: Well, I think that compliment should extend to the licensee also.

MEMBER SKILLMAN: Oh, yes. That's what I was trying to say to the Dominion team. Thank you.

1	MEMBER POWERS: Sure.
2	CHAIR ARMIJO: All right. Thank you,
3	Dana. Thank the staff. We're now going to take a
4	break and we'll reconvene at 10:30.
5	(Whereupon, the above-entitle matter went
6	off the record at 10:17 a.m.)
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	